

**METHOD STATEMENT**

**1) SCREEDING**

Area is cleaned and prepared.

**1a) Latex Screed**

Mix Screed powder into the equivalent Liquid;

Latex and apply to the floor to the required depth;

Allow to dry and grind down to the required finish.

**1b) Tools Required**

Bucket, Drill, Wisk, Trowel, Grinder, 110 V Transformer, 110 Extension Leads, Goggles, Mask

**RISK ASSESSMENT**

Minimal, as protection provided;

**Signed:** .....

**Position:** .....

**Date:** .....